

Product Announcement

HPE Aruba Networking is currently planning for the End of Sale of the following SKUs on the End of Sale date below (or until supplies are depleted) and customers are requested to migrate to the appropriate replacement.

The 8360 products are going end of sale as the 8360v2 products, which are the replacement products with key technology upgrades, were made available on Mar 7, 2022.

The 8360v2 includes these key technology upgrades:

1. 8360v2 supports 50G for these SKUs: JL702C/JL703C, JL700C/JL701C and JL704/JL705C.
2. 8360v2 supports Smart Rate ports with the JL706C and JL707C.

End of Sale Milestones:

- End of Sale External Announcement Date: **Aug 22, 2022**
- End of Sale Date: **Feb 28, 2023**
- End of Support Life (EoS) Date: **Feb 28, 2031***
- End of Warranty date: **Feb 28, 2031***

The 8360 and its 8360v2 replacement are the following:

8360 SKU EoS	8360 Product Description of SKUs going End of Sale	8360v2 SKU Replacement	8360v2 Replacement Product Description
JL700A	Aruba 8360-32Y4C Prt2Pwr3F2PS Bdl	JL700C	Aruba 8360-32Y4C v2 FB 3F 2AC Bdl
JL701A	Aruba 8360-32Y4C Pwr2Prt3F2PS Bdl	JL701C	Aruba 8360-32Y4C v2 BF 3F 2AC Bdl
JL702A	Aruba 8360-16Y2C Prt2Pwr3F2PS Bdl	JL702C	Aruba 8360-16Y2C v2 FB 3F 2AC Bdl
JL703A	Aruba 8360-16Y2C Pwr2Prt3F2PS Bdl	JL703C	Aruba 8360-16Y2C v2 BF 3F 2AC Bdl
JL706A	Aruba 8360-48XT4C Prt2Pwr3F2PS Bdl	JL706C	Aruba 8360-48XT4C v2 FB 3F 2AC Bdl
JL707A	Aruba 8360-48XT4C Pwr2Prt3F2PS Bdl	JL707C	Aruba 8360-48XT4C v2 BF 3F 2AC Bdl
JL708A	Aruba 8360-12C Prt2Pwr3F2PS Bdl	JL708C	Aruba 8360-12C v2 FB 3F 2AC Bdl
JL709A	Aruba 8360-12C Pwr2Prt3F2PS Bdl	JL709C	Aruba 8360-12C v2 BF 3F 2AC Bdl
JL710A	Aruba 8360-24XF2C Prt2Pwr3F2PS Bdl	JL710C	Aruba 8360-24XF2C v2 FB 3F 2AC Bdl
JL711A	Aruba 8360-24XF2C Pwr2Prt3F2PS Bdl	JL711C	Aruba 8360-24XF2C v2BF 3F 2AC Bdl

* The 8360 EoS and End of Warranty Dates will be updated to match the 8360 v2 (replacement product) EoS and End of Warranty Dates if greater than the dates contained in this document.

There will be no final orders accepted for the 8360 as the 8360 units are not available, or exhausted. Customers should order the 8360v2, see column showing “8360v2 SKU Replacement”. The 8360v2 offers the same software features, including key technology upgrades.

For questions regarding this End of Sale (EoS) Announcement, contact aruba-EoS@hpe.com.